



## REQUEST FOR PRICE QUOTATION

08 April 2021

### Repair and Preventive Maintenance Service of Three (3) Units POEA Service Vehicle (RFQ 06-2021)

Date: \_\_\_\_\_  
Name of Company: \_\_\_\_\_  
Address: \_\_\_\_\_  
Business Permit No. \_\_\_\_\_  
TIN: \_\_\_\_\_  
PhilGEPS Registration No.: \_\_\_\_\_

Please quote your lowest net price, taxes included for the item/s described below and submit your **signed and sealed** quotation to the POEA BAC Secretariat, BFO Building, Ortigas Ave., cor Edsa, Mandaluyong City not later than 2:00 P.M. on **16 April 2021** at which date and time, all submitted quotations will be opened. Late bids shall not be accepted.

  
**VIRGILIO L. CARREON JR.,**  
Chairperson  
Bids and Awards Committee

After having carefully read and accepted the Terms and Conditions, I/we submit our quotation/s for the item/s as follows:

QTY./ UNIT	DESCRIPTION	Approve Budget for the Contract	UNIT PRICE	TOTAL PRICE
	<p>Repair of One (1) unit POEA Service Vehicle Toyota Innova "E" with Plate no. SHJ 706</p> <p>Check, clean and repair brake system</p> <p>2 pcs. Reface front rotor disc (lh/rh) 2 pcs. Replace rear brake drum (lh/rh) 1 set Replace front brake pad (lh/rh) 1 set Replace rear brake shoe (lh/rh) 4 pcs. Replace rear brake wheel boot (lh/rh) 4 pcs. Replace rear brake wheel cap (lh/rh) Replace cylinder head gasket OBN</p> <p>Mechanical: Overhaul brake system Parts: 1 set Brake shoe 1 set Brake Pad 4 pcs. Wheel boot lh/rh rear 4 pcs. Wheel cap lh/rh rear 2 pcs. Front brake rotor disc lh/rh 2 pcs. Rear brake drum lh/rh</p>	P20,740.00		

	<p>1 pc. Cylinder head gasket</p> <p>1 lot Check, clean and repair brake system Parts to be replaced: 2 pcs. Reface rotor disc 2 pcs. Rear brake drum 1 set Front brake pad 1 set Rear brake shoe 4 pcs. Rear brake wheel boot 4 pcs. Rear brake wheel cap 1 pc. Cylinder head gasket</p> <p>Mechanical work: Remove and replace defective Parts</p>			
	<p><b>Repair of One (1) unit POEA Service Vehicle Toyota Innova "E" with Plate no. SJC 923</b></p> <p>Check, clean and repair brake system 2 pcs. Replace front rotor disc (lh/rh) 2 pcs. Replace rear brake drum (lh/rh) 1 set Replace front brake pad (lh/rh) 1 set Replace rear brake shoe (lh/rh) 4 pcs. Replace rear brake wheel boot (lh/rh) 4 pcs. Replace rear brake wheel cap (lh/rh)</p> <p>Mechanical: Overhaul brake system Parts: 1 set Brake shoe 1 set Brake Pad 4 pcs. Wheel boot lh/rh rear 4 pcs. Wheel cap lh/rh rear 2 pcs. Front brake rotor disc lh/rh 2 pcs. Rear brake drum lh/rh</p> <p>1 lot Check, clean and repair brake system Parts to be replaced: 2 pcs. Reface rotor disc 2 pcs. Rear brake drum 1 set Front brake pad 1 set Rear brake shoe 4 pcs. Rear brake wheel boot 4 pcs. Rear brake wheel cap</p> <p>Mechanical works: Remove and replace defective parts</p>	P15,940.00		
	<p><b>Repair of One (1) unit POEA Service Vehicle Toyota Innova "E" with Plate no. SHU 466</b></p> <p>Mechanical :</p> <ul style="list-style-type: none"> <li>• Replace front and rear shock absorber</li> <li>• Replace serpentine belt, idler bearing and tensioner bearing</li> <li>• Replace steering wheel siren ribbon, turbo air cleaner hose</li> <li>• Replace front brake pad and rear brake shoe</li> </ul> <p>Parts: 1 pc. Serpentine belt 2 pcs. Shock absorber lh/rh front 2 pcs. Shock absorber lh/rh rear 2 pcs. Idler bearing 1 pc. Tensioner bearing 1 pc. Siren ribbon of steering wheel 1 pc. Air cleaner hose of Turbo 1 set Brake shoe 1 set Front brake pad</p> <p>2 pcs. Replace front shock absorber (lh/rh) 2 pcs. Replace rear shock absorber (lh/rh)</p>	P41,600.00		



	2 pcs. Replace idler bearing 1 pc. Replace tensioner bearing 1 pc. Replace steering wheel/ Siren ribbon (for horn) 1 pc. Replace Turbo/ Air cleaner hose 1 pc. Replace serpentine belt 1 lot Labor Repair brake system 1 set Replace front brake pad (lh/rh) 1 set Replace rear brake shoe (lh/rh)  1 lot Check, clean and repair brake system Parts to be replaced: 2 pcs. Front shock absorber 2 pcs. Rear shock absorber 2 pcs. Idler bearing 1 pc. Tensioner bearing 1 pc. Steering wheel/ Siren ribbon 1 pc. Turbo/ Air cleaner hose 1 pc. Serpentine belt 1 set Front brake pad 1 set Rear brake shoe  Mechanical works: Remove and replace defective parts			
	<b>TOTAL</b>	P78,280.00		
Name of Company				
Complete Address				
Telephone No./Fax				
Printed Name of Owner/Authorized Representative and Signature				

**TERMS AND CONDITIONS:**

1. Bidders shall provide correct and accurate information required in this form.
2. Price quotation/s must be valid for a period of *Thirty (30) calendar days* from the date of submission.
3. Price quotation/s, to be denominated in Philippine peso shall include all taxes, duties and/or levies payable.
4. Quotations exceeding the Approved Budget for the Contract shall be rejected.
5. Award of contract shall be made to the lowest quotation which complies with the minimum technical specifications
6. Any interlineations, erasures or overwriting shall be valid only if they are signed or initialed by your or any of your duly authorized representative/s.
7. The POEA shall have the right to inspect and/or to test the goods to confirm their conformity to the technical specifications.
8. Liquidated damages equivalent to one tenth of one percent (0.001%) of the value of the goods not delivered within the prescribed delivery period shall be imposed per day of delay. The POEA may rescind or terminate the contract once the cumulative amount of liquidated damages reaches ten percent (10%) of the amount of the contract, without prejudice to other courses of action and remedies available under circumstances.

9. The bidder shall submit the following requirements:
  - a) Business Permit/Mayor's Permit:
  - b) PhilGEPS Registration; and
  - c) Notarized Omnibus Sworn Statement (See attached Revised Form).